Prepared (also subject responsible if other)		No.		
R&D MX-ONE Arne Miler		109 21-CAA 158 0067-15 Uen		
Approved	Checked	Date	Rev	Reference
R&D MX-ONE (Ulf Södermark)		2013-07-04	A	

Firmware for Aastra 7433ip and 7434ip, R2J

1 Reason for revision

This version of the application firmware shall be used in DBC 433 01 (Aastra 7433ip) and in DBC 434 01 (Aastra 7434ip).

New functionality

- **Secure FTP (SFTP).** It is possible to use a SFTP server to store the user specific data (.xml files). One new parameter is included in the configuration file.
- **Missed Call Indication:** When a user has a feature like parallel ringing or multiple terminal services, a call is marked as a missed call although it is answered on another phone. It is now possible to set a time in ringing state before an incoming call is regarded as a missed call. One new parameter is included in the configuration file.
- **Missed Call Indication:** It is possible to disable the missed call indication for the telephone via a new menu.
- **Message Menu Key.** It is possible to access voice mail with one key pressing. The sub menu with my messages / voice mail is not shown. One new parameter is included in the configuration file
- **Disable the Reject Key.** The Reject soft key and hard key can be disabled. One new parameter is included in the configuration file.
- **Set Display Type in an Attached Display Panel Unit.** Only in Aastra 7434ip. This option is only used in manufacturing or in the repair chain.
- **Recording Tone:** A recording tone can be enabled via configure file to indicate that the recording is on. New parameters are included in the configuration file.

Fault corrections.

- **OMD**. The phone used as an OMD stopped sending *Registration Request* message. TR-82130, GS-133615.
- **Locked up**. The phone was locked up when it received a new ip address from DHCP. TR-81737, GS-132984.
- **OMD**. When using the phone as an operator media device (OMD), the ring signal was too loud at incoming call. TR81884, GS-131349.
- **Reboot**. The phone could in one traffic case keep rebooting. TR-81221, GS-132371.

- **OMD**. Using the phone with OWS, it was difficult to present mark. TR-82127, GS-133615.

2 Technical solution.

Replace the current application and language file with:

Unit	Product number	From	To
Application	CAA 158 0067	R2H	R2J
Language file	CAA 158 0063	R2E	R2F

3 Other products concerned

Configuration file **CAA158 0064 R2J** (see below).

4 Reference

ECO 301027.

5 Recommended measures

The new configuration file **R2J** contains new parameter values. At upgrading the recommendation is to use the new configuration file and adapt it with all site dependent parameter values.

This revision of the firmware is to be introduced in new manufacturing.